

Supplemental Type Certificate

Number SR00891LA

This Certificate issued to Stephen C. Murray
2016 Palomar Airport Road
Hangar A
Carlsbad, California 92008

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 27 of the Federal Aviation Regulations.* *Certification basis is set forth in Type Certificate Data Sheet H2SW

Original Product Type Certificate Number: H2SW

Make: Bell Helicopter Textron

Model: 206, 206A, 206A-1, 206B, 206B-1, 206L, 206L-1,
206L-3, 206L-4, 407

Description of Type Design Change: Installation of aft utility mount, in accordance with FAA Approved Master Data List, Aero Pacific Document Number 407UM01-30, Revision "NEW" dated October 1, 2001, or later FAA Approved Revisions. FAA Approved Flight Manual Supplement Document Number 407UM01-10 dated December 20, 1999 or later FAA Approved Revisions is required for this installation.

Limitations and Conditions: The installation should not be incorporated in any aircraft unless it is determined that the interrelationship between this installation and any previously approved configuration will not introduce any adverse effect upon the airworthiness of the aircraft. The approval of this modification applies to the above noted airplane model series only. A copy of this STC must be included in the permanent records of the modified aircraft. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: October 5, 1998

Date reissued:

Date of issuance: December 20, 1999

Date amended: October 2, 2001, August 13, 2002



By direction of the Administrator

(Signature)
ACT:MSB Manager, Airframe Branch
Los Angeles Aircraft Certification Office

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.